StarFire[™] 6000 & StarFire[™] 6000 Integrated Receiver

Resolved Items:

AutoTrac[™] Kicks out with "No TCM Corrections" Message Received – Upon engaging AutoTrac[™] with a StarFire[™] 6000 receiver in a 00/10/20 series tractor, AutoTrac[™] disengages after a few seconds with the message "No TCM Corrections". This software update will resolve this issue.

Direction Change Displayed Incorrectly in Slow Speed Integrated AutoTrac™ – When traveling at slow speeds (below 0.5 kph/0.3 mph) and changing direction, direction of travel may not display correctly. This software update reduces the minimum speed from 0.5 kph to 0.1 kph for the system to determine correct direction of travel and resolve heading issues.

AutoTrac[™] Universal 300

Resolved Items:

Steering calibration operator override message – This software version provides an update to the steering calibration operator override message.

Motor information updates with change to display language – The motor information now updates with all current information if the user decides to switch languages and not perform a cold boot.

Application Controller 1100 (S.N. PCXL01B100000 -) & Application Controller 1120 (S.N. PCXL02B100000 -)

Resolved Items:

iGrade[™] and Active Implement Guidance will not function – This release fixes an issue where using a universal receiver on a tractor that has an integrated receiver causes iGrade[™] and Active Implement Guidance to not function.

Application Controller 1100 (S.N. PCXL01C201000 -) & Application Controller 1120 (S.N. PCXL02C201000 -)

Resolved Items:

iGrade[™] and Active Implement Guidance will not function – This release fixes an issue where using a universal receiver on a tractor that has an integrated receiver causes iGrade[™] and Active Implement Guidance to not function.

Application Controller crashes Implement CAN Bus – This software version resolves an issue where the Application Controller would cause the Implement CAN bus to crash when powered on.

GreenStar[™] 3 2630 Display

Resolved Items:

Implement Width

- Display will not produce a coverage map operating with implements configured with one zero width section.
- Grey Implement width bar disappears after 17-1 update.

Advanced AutoTrac[™] Settings – When using Reichhardt[®] advanced AutoTrac[™] settings, the increase and decrease buttons max out at 255 instead of 200 when pressed several times.

Universal Performance Monitor (UPM) – Universal Performance Monitor missing in dual display setup with Generation 4 CommandCenter[™].

Documentation – Yield and coverage maps are not retained after display shutdown.

Mapping – Gaps in Harvest Coverage Maps on combines running Active Yield.

Section Control

- When running Section Control with Slurry & Manure Constituent Sensing (MCS) combination, the MCS coverage map does not match the Slurry applicator.
- Section Control does not work with a connected Amazone Fertilizer.
- Display maps a section of false coverage causing gaps with Section Control, i.e. map flips.

Baler Automation – Baler automation will not engage with 3.19.1117 or newer 2630 software.

AutoTrac™ RowSense™ – When operating with RowSense™ enabled, in GPS-only mode, the AB line shift buttons will not shift the AB line causing the machine to steer onto the crop.

Receiver cab-offsets – StarFire receiver cab-offset shows on the wrong side for 6-walker combines.

Status Errors

- Status error 0.1CE8.00001 occurs when the display is connected to a 4G MTG LTE.
- Status error assertion failure 1.0640.00246.

Machine Sync Harvest Automation – Wireless Connection Error.

Release Notice

These are software release notes for GreenStar[™] 3 2630 and related products. Release Notes can be found on <u>www.stellarsupport.com</u>. Note: Your use of the software is governed by the End User License Agreement included with the software.

Copyright © 1996-2020 Deere & Company