

APEX™ Version 3.8.6.3964

Release Notes

Mobile Weather:

Mobile Weather data missing in APEX™ – This is likely caused by out of date Mobile Weather software. Mobile Weather station requires software version 1.51 or newer for Mobile Weather data to be recorded within .doc data.

Resolved Issues:

Merging Fields – User was previously unable to merge map layers and received error message “At item with the same key has already been added.” This issue has been resolved.

Changing crop type “Corn” to “Corn Silage” – User previously received an error message “Unhandled exception error has occurred in your application.” This issue has been resolved.

Global Support Center Information

www.stellarsupport.com

E-mail: GreenStar@JohnDeere.com

North America Activations only: 1-888-953-3373

North America Support: 1-888-GRN-STAR (1-888-476-7827)

Australia: 0011-800-833-3373

New Zealand: *(000911) 877-712-6449

Brazil: 0-800-891-4031

Mexico: 866-582-4068

Argentina: 0800-444-9126

South Africa: 0800-983-821

Zimbabwe: *(110-98990) 888-983-3373

Zambia: *(00-899) 888-923-3373

*Countries w/ access codes – Dial access code first and once prompted, enter the toll free number.

Copyright © 1996-2019 Deere & Company

Release Notice

These are the Release Notes for the APEX™ Version 3.8.6.3964 Release.